

THE ALDE & ORE ASSOCIATION

Maintain our Coast and River Defences



RIVER BANK ASSESSMENT FOR 2012

FLOOD CELL 3 - CHILLESFORD LODGE MARCHES

1 On the EA grading guide the majority of the wall appears to be in good condition (Grade 2), with one or two areas classed as fair (Grade 3). At the start of the wall () there is considerable high tide debris 1/3 of the way up the wall. The sward has been cut, no scrub and the landward slope has a fairly sharp incline but is in good condition.

2 The early part of the revetments are in good condition with minor collapses on Bay 9, 11 and 12



Bay 9



Bay 11



Bay 12

3 Area of approx 2 metres of interlocking revetment collapse ()



4 Considerable debris so unable to inspect toe.



THE ALDE & ORE ASSOCIATION

Maintain our Coast and River Defences



5 200 metres from Greenwell Estate boundary there is an area of bare earth above the revetments and just before the boundary on the landward bank several mole hills.



6 The landward slope is good with a tight sward. Approx 150 metres from Watson Estate boundary there are vehicle tracks in the crest.



7 100 metres from the field gate there are burrows and minor slippage to the river frontage of the wall.

