

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1064789



ALDE AND ORE ESTUARY ASSESSORS' REPORT

NAME:	Roger Baxter Jane Salter	DATE OF INSPECTION:	April 2015
LOCATION:	Flood Cell 2	March Equinox	
AREA OF ASSESSMENT:	Butley Mills, Mill Lane, Butley		

River bank surveyed



SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Good condition with good grass coverage on all slopes	Deep marsh bed	None

OVERVIEW

- The river wall is in a good state of repair following recent, but substantial refurbishment.
- New grass has established well on all slopes.
- There are two controllable sluices
- Reed beds are substantial all the way down to the low water level on the river

Wall top with good width and vegetation coming through. TM386515



One of two sluices. Deep reed beds TM386519



Mills on other side of the lane. TM386519 looking North

