


# THE ALDE & ORE ASSOCIATION

Registered Charity No. 1064789



## ALDE AND ORE ESTAURY RIVER ASSESSMENT 2015

<b>NAME: Amanda Bettinson/ Sally Walton</b>	<b>DATE OF INSPECTION</b>
<b>LOCATION: Flood Cell 3</b>	<b>17th APRIL 2015</b>
<b>FROM: Ferry Cottage to Chillesford Lodge travelling North</b>	

River wall inspected



1. Because of the wire fence the river armour can only be seen from above.



2. 396 498

Three metres of sunken Essex block





3. At 395 498

Three metres of sunken Essex block



4. At 396 499

Grass growing up by old alder posts.



5. 395 502

Three metres sunken of Essex block straddling the transverse joint support



6. 394 502/3

Two metres of sunken interlocking blocks followed by sunken Essex block







7. 393 503 (just before Saltings)

One Essex block worn away, and another 3 yards further along.



The tide line is 2/3 way up the wall.

Landward slope in the main is good, with some areas rather too steep. Potential areas for saltings should be assessed.

SW/AJB