


THE ALDE & ORE ASSOCIATION


Registered Charity No. 1064789



ALDE AND ORE ESTUARY ASSESSORS' REPORT

NAME: Frances Barnwell and Diana Paterson	DATE OF INSPECTION 3 rd April 2014
LOCATION: Flood Cell 4.2	MARCH/SEPTEMBER/TIDAL EVENT
Area of Assessment: Orford Sailing Club to Chantry Point	Send to

River wall inspected



1. Although dry and hard when inspected, the path gets very muddy and slippery in wet weather. It has become eroded in areas of high usage between Orford Quay and the pillbox, especially by the steps near the quay (TM 4243 4950), the manhole cover (TM 4233 4912) and the first stile (TM 4241 4873).



2. There is a significant dip either side of the manhole cover (TM 4233 4912) and where a path has formed down the inland bank



3. There is a significant dip by the stile (TM 4241 4873).



- 4 Small revetment collapse at the stile (TM 4241 4873). This was reported in 2013.



5. We were also asked to inspect the river wall between Orford Quay and Orford Sailing Club. There is evidence of slump to seaward by the Sailing Club dinghy park (TM 4266 4963).



6. The path east of Orford Sailing Club (by The Pavilion) shows damage to the hoggin surface and gets very muddy when wet (TM 4266 4963).

