

Registered Charity No. 1064789



ALDE AND ORE ESTUARY ASSESSORS' REPORT

NAME: Simon Reid Roger Baxter Rufus Gilday	DATE OF INSPECTION: April 2015
LOCATION: Flood Cell 4.3	March Equinox
AREA OF ASSESSMENT: Pump House on West Bank to Orford Town	

River wall inspected



SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Good	Some erosion	None

OVERVIEW

- Mostly robust river wall with strong back slopes, although some erosion of saltings (443517).
- Hole on top of wall (449 524) unchanged from last year.
- Erosion at foot of wall (443 518), again, unchanged from last year.
- Sheep grazing assisting strong vegetation.

Hole on wall top at 449 524. No change since last year



Revetment erosion at 443 518

