

# THE ALDE & ORE ASSOCIATION


Registered Charity No. 1064789



## ALDE AND ORE ESTUARY ASSESSORS' REPORT

<b>NAME:</b>	<b>Roger Baxter Rufus Gilday Simon Reid</b>	<b>DATE OF INSPECTION:</b>	<b>April 2015</b>
<b>LOCATION:</b>	<b>Flood Cell 4.4</b>	<b>March Equinox</b>	
<b>AREA OF ASSESSMENT:</b>	<b>Chapmans Creek to Pump House</b>		

### River wall inspected



## SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Good with no overtopping	Mostly substantial	None
	Attenuation system to be continually monitored	
Revetment collapse in a small area	Narrow in isolated areas	-
Minor concern only	Continue monitoring	-

## OVERVIEW

- River walls are in good condition, with dense vegetation. Where sheep have been grazing, grass is short and healthy.
- Mole damage reported last year is no longer evident.
- Saltings mostly deep, although narrow in the area where electric fences are in place (457545)
- Erosion of revetments at 457543 has not worsened.
- Attenuation system at Ferry Point to be monitored.

Typical front slope with good vegetation



Lack of saltings in some areas.

