

# RDC survey 2013

## Flood Cell 2 – Butley Mills

Section inspected by Frances and David Barnwell 5 May 2013

---

1. Walking north from Butley Mills, the first section by the barns at TM 3858 5159 is in reasonable condition with some small trees



2. The new work at TM 3858 5194 is mown and in good condition



3. This is followed by heavily wooded and overgrown sections at TM 3858 5194



4. The final section by Chillesford at TM 3861 5211 is overgrown

