

FC 1 Surge Report

FLOOD CELL 1.I have walked the river bank from 379447 to Butley Ferry. No damage to levees, evidence of overtopping between Flybury Point and junction with Butley River and continuing for app. 200M along Butley River wall (but not continuous overtopping,) Some further undermining of protection around Boyton Dock since inspection in March, not sure if this is surge damage or normal tidal wear.



B Johnson Dec 2013