


# THE ALDE & ORE ASSOCIATION

Registered Charity No. 1064789



*The Association exists to preserve for the Public benefit the Alde, Ore and Butley Creek rivers and their banks from Shingle Street to their tidal limits and such of the land adjoining them or upstream as may be considered to affect them, together with the features of beauty and or historic or public interest in that area.*


## ALDE AND ORE ESTUARY ASSESSORS' REPORT

<b>NAME:</b> Simon Reid and Maggie Scorer	<b>DATE OF INSPECTION:</b> 10 <sup>th</sup> April 2014
<b>LOCATION:</b> Flood Cell 4.3	<b>MARCH EQUINOX</b>
<b>AREA OF ASSESSMENT:</b> Orford Town north to pump station on west bank of river GR	

### SUMMARY

<b>River Wall /Armour</b>	<b>Saltings</b>	<b>High Tide Debris Line</b>
Nearly all in good shape except where mentioned below	Signs of saltings being eroded	None visible

## River bank surveyed



## OVERVIEW

Erosion of saltings GR 443 517 (note electric fence to keep animals out)



A hole on top of the wall (been there for at least three years) GR 449 524:





Again more example s of foot of  
wall erosion GR 443 518

