



ALDE AND ORE ESTUARY ASSESSORS' REPORT

NAME: Keith Martin and Simon Barrow	DATE OF INSPECTION 7th April 2015
LOCATION: Flood Cell 5	MARCH equinox
Area of Assessment Chapman's Creek to The Anchorage, Iken	

River bank surveyed



with thanks to landowners Paul Cooke, Richard Mann, John and Gunilla Hailes



1. Landowner, Paul Cooke

443 560 No sign of the serious near breach now repaired . However, long stretch of little or no saltings and needs support for saltings development.



442 562 The height of this section seems low. Check height

441 568 (opposite Hazlewood Marshes when the wall turns west) Needs support for saltings development



438 567 damaged and buckled armour in several places and little or no saltings



434 563 evidence of a mini slip just below the crest on the land side of the wall



433 563 damaged armour (in the second bay opposite Hazlewood)



430 562 recent new armour looks ok

2. Landowner, Richard Mann

428 563 No sign of major repairs to three near breaches post Dec 2013

Some saltings support needed



3. Landowners, John and Gunilla Hailes

424 567 Wall in good shape but restricted saltings

417 567 Wall in good shape and extensive new post and electric fencing to enclose sheep on the landside bank so grass short

